



E202 WELDING CART SET UP INSTRUCTIONS


Step 1 Unpack cart and perform installations as indicated by arrows.




Step 2 Attach wire bracket to top shelf.




Step 3 Attach water tank brackets to water tank.




Step 4 Place water tank on bottom base and secure it in place.




Step 5 Top water tank with welder, have the welder aligned and secured.



Step 6 Attach support brackets to welder.



Step 7 Attach top shelf to cart and complete full assembly.



Top shelf

Use four M5 screws for fastening.

Use eight M8 screws for fastening.