




## Spare parts &amp; accessories for 3M™ Speedglas™ Welding Helmet 9100 FX Air



## Auto-darkening lens



## Passive lens option



Part No	Description	Part No	Description	Part No	Description
11 00 10	Lens Welding Shade 10 Passive 90X110mm 9100	19 71 44	Flip Up Mechanism 9100 FX Pk=2	53 35 05	Adaptor Adflo Breathing Tube 9100 Air, FX Air & MP Air
11 00 11	Lens Welding Shade 11 Passive 90X110mm 9100	42 20 00	Battery Lithium 9100, 100 & 9000 Pk=2	53 40 00	Face Seal 9100 FX Air
11 00 12	Lens Welding Shade 12 Passive 90X110mm 9100	50 00 01	Lens Welding Filter 9100P Shade 11 Passive	53 50 00	Air Deflector 9100 FX Air
11 00 13	Lens Welding Shade 13 Passive 90X110mm 9100	50 00 26	Lens Welding 9100XXi Speedglas	53 60 00	Head Harness Pivot Mechanism 9100
16 90 06	Head Cover Small 9100 FX	52 30 00	Visor Plate 9100 FX & MP Pk=5	53 61 00	Head Harness Front Part 9100
16 90 07	Head Cover Large 9100 FX	52 30 01	Visor Plate Anti-Fog 9100 FX & MP Pk=5	53 62 00	Head Harness Back Part 9100
16 90 10	Throat Protection 9100	52 60 00	Lens Cover Outer Standard 9100 Pk=10	54 05 00	Front Cover Kit 9100 FX & MP
16 91 00	Head Cape Tecaweld	52 70 00	Lens Cover Outer Hard Coated 9100 Pk=10	54 28 00	Helmet Welding 9100 FX Air Exc Lens
16 95 02	Sweatband 9100 & 9100 FX Pk=2	52 70 70	Lens Cover Outer High Heat 9100 Pk=10	54 77 00	Speedglas 9100 FX Air with Adflo, Exc Welding Lens & Bag
16 95 05	Sweatband 9100 & 9100 FX Pk=5	52 80 01	Lens Cover Inner 9100 Passive Pk=5	54 88 00	Speedglas 9100 FX Air with V-500E, Exc Welding Lens & Bag
16 95 50	Sweatband 9100 & 9100 FX Pk=50	52 80 05	Lens Cover Inner 9100V Pk=5	54 90 26	Speedglas 9100XXi FX Air Upgrade Kit, Exc Adflo
17 10 20	Lens Magnifying 1.0X 9100, 100 & 9000	52 80 15	Lens Cover Inner 9100X Pk=5	79 01 01	Carry Bag Speedglas
17 10 21	Lens Magnifying 1.5X 9100, 100 & 9000	52 80 25	Lens Cover Inner 9100XX/XXi Pk=5	83 40 19	Breathing Tube Cover Flame Resistant 9100 FX Air
17 10 22	Lens Magnifying 2.0X 9100, 100 & 9000	53 10 00	Holder Battery 9100		
17 10 23	Lens Magnifying 2.5X 9100, 100 & 9000	53 20 16	SideWindows Cover Plate 9100 FX & MP Pk=2		
17 10 24	Lens Magnifying 3.0X 9100, 100 & 9000	53 30 00	Head Harness 9100		
		53 35 00	Air Duct Assembly 9100 FX Air		